

## IMPORTANT SAFETY ALERT

### PRODUCT SAFETY REPAIR

#### Kitchen Plus Gas Hob



We have become aware that some Kitchen Plus gas hobs may be fitted with a connector that is at risk of failing in certain circumstances whether the hob is in use or not. Should this occur, this could lead to a gas leak or fire.

The model affected has the following model numbers:

**KP60**

#### **How do know if I have an affected model?**

The model number can be found either on the rating label under the hob, or on the instruction manual. Should neither be readily accessible, or you have concerns you might have an affected model, then please follow the instructions below to register for a free inspection by a Gas Safe registered engineer.

#### **What should I do next?**

**If you have an affected gas hob or you cannot locate your model number, it's important that you contact us straight away to arrange for a free inspection and repair by a Gas Safe Registered engineer. You can contact us on our hotline number 01473 292862.** Alternatively, go to [gashobsrepair.mktpoint.com](http://gashobsrepair.mktpoint.com) to enter your details. When contacting us, please have your model number to hand.

**If you are using an affected appliance with Liquid Petroleum Gas (LPG) in a caravan or motorhome, please disconnect it from the LPG cylinder immediately.**

If you have any queries, please do not hesitate to contact us on **our hotline number 01473 292862** or email [KP60@munroimporters.co.uk](mailto:KP60@munroimporters.co.uk).